



WIRING DIAGRAM FOR OPERATING ONE SINGLE FIXTURE

A. WITH 0-10V DIMMER




USE COPPER WIRE

B WITHOUT 0-10V DIMMER



USE COPPER WIRE


C. IF THE 0 - 10 V AUTO DIMMING FEATURE IS USED, BUT EXTERNAL 0 - 10 V DIMMING CTRL IS NOT USED, THEN ONLY CAP OFF THE RED/WHITE AND BLUE/WHITE WIRES.



USE COPPER WIRE

WIRING DIAGRAM FOR OPERATING MULTIPLE FIXTURES


D. FOR OPERATING MULTIPLE FIXTURES



USE COPPER WIRE


DIAGRAMA DE CABLEADO PARA OPERAR UNA SOLA ACCESORIO DE ILLUMINACION

A. CON ATENUADOR DE 0-10V




USAR CABLE DE COBRE

B SIN ATENUADOR DE CA NORMAL



USAR CABLE DE COBRE


C. SI SE UTILIZA LA FUNCIÓN DE ATENUACIÓN AUTOMÁTICA DE 0-10 V, PERO NO SE UTILIZA EL CONTROL DE ATENUACIÓN EXTERNO DE 0-10 V, ENTONCES SOLO TAPE LOS CABLES ROJO/BLANCO Y AZUL/BLANCO.



USAR CABLE DE COBRE

DIAGRAMA DE CABLEADO PARA OPERAR MÚLTIPLES ACCESORIOS

D. PARA OPERAR MÚLTIPLES ACCESORIOS



USAR CABLE DE COBRE