



**WIRING DIAGRAM FOR OPERATING ONE SINGLE FIXTURE**

**A. WITH 0-10V DIMMER**




USE COPPER WIRE

**B WITHOUT 0-10V DIMMER**



USE COPPER WIRE


**C. IF THE 0 - 10 V AUTO DIMMING FEATURE IS USED, BUT EXTERNAL 0 - 10 V DIMMING CTRL IS NOT USED, THEN ONLY CAP OFF THE RED/WHITE AND BLUE/WHITE WIRES.**



USE COPPER WIRE

**WIRING DIAGRAM FOR OPERATING MULTIPLE FIXTURES**


**D. FOR OPERATING MULTIPLE FIXTURES**



USE COPPER WIRE


**DIAGRAMA DE CABLEADO PARA OPERAR UNA SOLA ACCESORIO DE ILLUMINACION**

**A. CON ATENUADOR DE 0-10V**




USAR CABLE DE COBRE

**B SIN ATENUADOR DE CA NORMAL**



USAR CABLE DE COBRE


**C. SI SE UTILIZA LA FUNCIÓN DE ATENUACIÓN AUTOMÁTICA DE 0-10 V, PERO NO SE UTILIZA EL CONTROL DE ATENUACIÓN EXTERNO DE 0-10 V, ENTONCES SOLO TAPE LOS CABLES ROJO/BLANCO Y AZUL/BLANCO.**



USAR CABLE DE COBRE

**DIAGRAMA DE CABLEADO PARA OPERAR MÚLTIPLES ACCESORIOS**

**D. PARA OPERAR MÚLTIPLES ACCESORIOS**



USAR CABLE DE COBRE